



Restoration Period Clock In Gilt Bronze With A Young Woman



3 100 EUR

Period : 19th century

Condition : En bon état général. usure du temps à la dorure.
mécanisme révisé et en état de fonctionnement.

Material : Bronze

Width : 31

Height : 47

Depth : 14

Description

Clock in gilded and patinated bronze representing a young woman seated on a rock. Work from the Restoration period, at the beginning of the 19th century.

In good condition. Time wear to the gilding.
Mechanism revised and in working order.

[Read more](#)

Dealer

Galerie Atena

Decorative Arts and Furniture

Mobile : 06 17 08 51 58

Château de Peyraud, 277 allée du Château de Peyraud, 07340,
Peyraud / Galerie sur RDV au 8 rue de Miromesnil à Paris
Paris 75008